




Leg Attachment Kit

Part #WIN-3700

used on Winchester units



- Make sure unit is turned off and cooled down.
- Carefully tip unit onto the back.
- Using the mounting pads and diagram shown below, position pads as shown.



- Mount the legs with the $\frac{1}{4}$ -20 x 2 $\frac{1}{4}$ " hex bolts and washers supplied through the leg, pad and base.

- Restart unit.

