


Auger Delron Bushing between Auger and Auger Plate

Product Models Covered: ALL MagnuM Baby Countryside & Winchester models



What to look for: There has been a new delron bushing with a longer flange that extends toward the auger motor installed between the auger and auger plate. This is to help alleviate the play between the auger and auger plate so that the bushing does not fall out of the plate.

You will be able to tell if you have an upgraded delron bushing by looking at the serial number, located on the back of the unit. If the serial number is greater than # 13870 (for the MagnuM Baby Countrysides) you have the upgraded delron bushing in the unit. There is no need for current owners to upgrade to the new delron bushing, however if they want to upgrade they can purchase it from their local dealer. The part number is P1178